

This snowpit shows a faceted layer just under an ice crust about 2ft deep. It is not a major concern as it does not have enough stress from recent snow to produce widespread avalanches. However, its ability to propagate fractures (ECTP) is a red flag that tells us human triggered avalanches are definitely possible. Check the videos from Feb 17th and Feb 6th.

Advisory Region
Northern Gallatin
Northern Gallatin, 2011-02-18